

PCB EDITOR

Keyboard Shortcut Cheat Sheet

Zooms/View

Zoom Fit:	F2
Zoom In:	F11
Zoom Out:	F12
Zoom Previous:	⇧F11
Zoom World:	⇧F12
New:	^N
Open:	^O

Popular Commands

Add Connect:	F3	Grid Toggle:	F10	Copy:	⇧F5
Show Element:	F4	Color Dialog Box:	^F5	Move:	⇧F6
Redraw:	F5	Property Edit:	⇧F2	Dehighlight All:	⇧F7
Done:	F6	Slide:	⇧F3	Highlight Pick:	⇧F8
Next:	F7	Show Measure:	⇧F4	Vertex:	⇧F9
Oops:	F8	Rotate:	R	Save As Temp:	⇧F10
Cancel:	F9	Pan:	↔	Delete:	^D